




1/17






FIG. 2

3/17

Serial Port Settings	
Serial Port:	<input checked="" type="radio"/> 1 <input type="radio"/> 2
Port type:	RS-232 <input checked="" type="checkbox"/>
Baud rate:	9600 <input checked="" type="checkbox"/>
Data bits:	8 <input checked="" type="checkbox"/>
Parity:	None <input checked="" type="checkbox"/>
Stop bits:	1 <input checked="" type="checkbox"/>
Flow control:	None <input checked="" type="checkbox"/>
<input type="button" value="Submit"/> <input type="button" value="Cancel"/>	

FIG. 3

Flex I/O Port Settings					
Port	Mode	Pull-up	Threshold*	Lower* (0.25,3V)	Upper* (0.25,3V)
1	Digital Input	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	0.9	1.0
2	Digital Output	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
3	Digital Output	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
4	Digital Output	<input checked="" type="checkbox"/>	<input type="checkbox"/>		
<input type="button" value="Submit"/> <input type="button" value="Cancel"/>					

* Lower and Upper Threshold settings are for Digital Input only.

FIG. 4




FIG. 5

6/17




FIG. 6

7/17




FIG. 7

8/17




FIG. 8

9/17




FIG. 9

10/17




FIG. 10

11/17




FIG. 11A

12/17




FIG. 11B




FIG. 12

14/17




FIG. 13

15/17




FIG. 14




FIG. 15




FIG. 16